




Volume V

Appendix G.6

SRB Working Group Presentation to CAIB

This Appendix contains the SRB Working Group Presentation to Columbia Accident Investigation Board, 28 May 2003.

THIS PAGE INTENTIONALLY LEFT BLANK



SRB Working Group




SRB Working Group Presentation to Columbia Accident Investigation Board CAIB



Solid Rocket Booster Working Group Agenda

SRB Working Group



- Executive Summary
- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary


Preliminary - Investigation Sensitive

Page 2



Executive Summary

SRB Working Group



Objective

- To Determine if the Solid Rocket Boosters (SRBs) were a contributor to the loss of the STS-107 crew and vehicle.

Approach

- Develop credible Fault Tree failure scenarios for events that could have contributed to the loss of STS-107. Follow structured and methodical approach for closure of all fault tree blocks.
- Perform in-depth hardware and documentation assessment using all available analysis, test, recovered hardware inspection, pedigree documentation, processes, and discrepancy data.

Fault Tree Summary

- 509 blocks (including Top Level block) rolled up into 88 closure blocks

	Total Blocks	Closure Blocks	Multi-Element	Open Blocks
Load & Environments	70	18	1	0
Active Subsystems	14	2	3	0
Debris	424	68	35	4
Total	508	88	39	4


Page 3

Preliminary - Investigation Sensitive



Executive Summary

SRB Working Group



Fault Tree Closure Definitions

- **Closed** – Fault Tree Blocks in which the event or failure scenario has been deemed **Not Credible** by the SRBWG.

- **“Not Credible”** is defined as “Extremely remote possibility that Failure Scenario caused the loss of STS-107. Either strong controls in place or hardware evidence shows event did not occur.”

- **Open** – Fault Tree Blocks where SRBWG cannot obtain majority consensus on Failure Scenario being **“Not Credible.”**

-
- Fault Tree Block B.1.3.2.4.2 (Debris Ejection from Motor (FWD BSM)) – **Closed (Minority Report)**
 - Fault Tree Blocks B.1.3.4.4.3.1, B.1.3.4.4.3.2, B.1.3.4.4.3.3, B.1.3.4.4.3.4 (Bolt Catcher) – **Open** (Pending Test Results)
 - Fault Tree Block number B.1.3.6.1.1 (Loss of Aft Separation Area ET Side TPS Causes Debris) is **closed** based on engineering judgment by the SRBWG. Final Debris Transport Analysis from Level II is pending but is related to return-to-flight rather than fault tree closure..

Page 4

Preliminary - Investigation Sensitive



Executive Summary

Acronym List

ACO	Assembly Check Out
AFT	Rear of the spacecraft
AMS	Aerospace Material Specification
AP	Ammonium Perchlorate
APRT	Ascent Performance and Reconstruction Team
APU	Auxiliary Power Unit
ATVC	Ascent Thrust Vector Control
BET	Best Estimate Trajectory
BI	Booster Identifier
BSM	Booster Separation Motor
BT A	Booster Trowelable Ablative
CDF	Confined Detonating Fuse
CDF A	Confined Detonating Fuse Assembly
CDF I	Confined Detonating Fuse Initiator
CDF M	Confined Detonating Fuse Manifold
CIL	Critical Items List
CSD	Chemical Systems Division now known as P&W Space Propulsion
CWSI	Critical Weld Stress Indicator
DAS	Data Acquisition System
DCMA	Defense Contract Management Agency
E&I	Electrical and Instrumentation
EC P	Engineering Change Proposal
EC R	Engineering Change Request
ED	Engineering Directorate
EMI	Electromagnetic Interference
ESD	Electrostatic Discharge
ET	External Tank
ET A	External Tank Aft
FEM	Finite Element Mode
FEM	Finite Element Model
FEP	Fluorinated Ethylene Propylene
FIV	Fuel Isolation Valve
FMEA/CIL	Failure Mode and Effects Analyses/Critical Items List
FOD	Foreign Object Debris
FOS	Factor of Safety
FSM	Fuel Supply Module


FT	Fault Tree
FWD	Forward
GNC	Guidance, Navigation and Control
GO	Ground Operations
HDI	High Density Indication
HDP	Holddown Post
ICD	Interface Control Document
IPR	In Process Review
JSC	Johnson Space Center
KSC	Kennedy Space Center
L&E	Loads and Environment
LCC	Launch Commit Criteria
LH	Left Hand
LOV	Loss of Vehicle
LSBR	Liquid Strand Burn Rate
LSC	Linear Shaped Charge
MAF	Michoud Assembly Facility
MCC-1	Marshall Convergence Coating - 1
MET	Mission Elapsed Time
MLP	Mobile Launch Platform
MLP	Mobile Launcher Platform
MPP	Manufacturing Process Plan
MSFC	Marshall Space Flight Center
NDE	Nondestructive Evaluation
NIS	Nonconformance Information System
NSD	NASA Standard Detonator
NSI	NASA Standard Initiator
NSI-PC	NASA Standard Initiator - Pressure Cartridge
OMI	Operations and Maintenance Instructions
OMRSD	Operations and Maintenance Requirement Specification Document
P&W	Pratt and Whitney
PDL	Polymer Development Labs
PIC	Pyrotechnic Initiator Controllers
PR	Problem Report
PRCBD	Program Requirements Change Board Directive
PSC	Primary Separation Cue

Preliminary - Investigation Sensitive



Executive Summary

SRB Working Group



Acronym List

RCS	Reaction Control System
RH	Right Hand
ROD	Routing Operation Document
RSRM	Redesigned Solid Rocket Motor
RSS	Range Safety Systems
RTV	Room Temperature Vulcanizing
S&A	Safe and Arm
SIRB	Systems Integration Requirement Board
SLA	Super Light Ablator
SLET	Shelf Life Extension Test
SRB	Solid Rocket Booster
SRBTS	Solid Rocket Booster Tracking Subsystem
SRBWG	Solid Rocket Booster Working Group
SRM	Solid Rocket Motor
SSME	Space Shuttle Main Engine
SSP	Space Shuttle Program
TLI	Thrust Load Indicator
TPS	Thermal Protection System
TSM	Tail Service Mast
TVC	Thrust Vector Control
USA	United Space Alliance
USBI	United Space Booster, Incorporated
VAB	Vehicle Assembly Building
WADS	Work Authorization Documents


Preliminary - Investigation Sensitive

Page 6



Solid Rocket Booster Working Group Agenda

SRB Working Group



- Executive Summary
- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary

Note: The symbol  indicates a link to back up information.


Preliminary - Investigation Sensitive

Page 7



Solid Rocket Booster Working Group Team Members

SRB Working Group



SRB Working Group (NASA Team)

Darrell Davis	Thermal
Joe B. Davis	Pyrotechnics
Jeff Dilg	Structures
Don Ford	Systems Engineering
Joe Gentry	Structures
Rusty Jones	Loads/Environments
Joe Lusk	SRBWG Deputy Chair and Assistant Project Manager, SRB Project Office
Tina Malone	M&P
Malissa Meadows	E&I
Boris Pagan	TVC
Tom Reickhoff	Photo Analysis
Pete Rodriguez	SRBWG Chair and Deputy Manager, Structures, Mechanics and Thermal Department
George Story	BSM
Randall Tucker	S&MA
Renee Wilson	SRBWG Secretary


Page 8

Preliminary - Investigation Sensitive



Other Key Players

SRB Working Group



Review and Assessment

Peggy Frazier
Chantel Jacob
Mike Norris

Systems Fault Tree Review Team

Joe Bruntz
Dan Mullane
Richard Sheppard
John Townsend

DCMA Key Players

Jim Anderson
Craig Bennett
Myles Campbell
Primo Correa
Carlos de Mattos
Joe Giedliński
Robert Kaufmann
Robert Kauffman
Dave Kedell
Ron Koehn
Norm Powers
Tom Root
Mike Smutek
Terence Young

NASA S&MA MSFC and KSC

Foster Anthony
Shane Canerday
Neal Hooten
Art Morales
Robert Osterblum
Rick Sizemore

NASA MSFC SRB Resident Office at KSC

Homero Hidalgo
Tom Engler
Robin Ferebee
Sandy Norris

SRBWG Senior Advisory Group

Vince Caruso(retired), Former Manager, Systems Management and Integration Office, Space Shuttle Main Engine
Keith Coates(retired), Former Chief Engineer, Solid Rocket Motor Program
Erich Engler(retired), Former Chief, Structural Development Branch, Science and Engineering Directorate
Bob Henry(retired), Former Senior Technical Assistant to the Chief Engineer, Solid Rocket Booster Program
Bill Horton(retired), Former Chief Engineer, Solid Rocket Booster Program

Senior Independent Review

Moody Davis(retired), Former Manager, Testing and Operations Office, Chief Engineer's Office, Solid Rocket Motor Program
Jim Thomas(retired), Former Manager, Technical Operations Office, Solid Rocket Motor Program

Fault Tree Independent Review


Robert Schwinghamer(retired), former Assistant Center Director - Technical, MSFC

Preliminary - Investigation Sensitive

Page 9




Solid Rocket Booster Working Group Team Members



SRB Working Group

USA Investigation Team Leads/Key Players



Preliminary - Investigation Sensitive

Page 10



Solid Rocket Booster Working Group Agenda

SRB Working Group



- Executive Summary
- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary


Preliminary - Investigation Sensitive

Page 11



Special Circumstances

SRB Working Group



- **Hardware Status As of February 1, 2003:**
 - Open Assessment of STS-107 SRB/RSRM Hardware Completed on 1/20/03
 - • The SRB/RSRM Disassembly Schedule Was Nearly Complete
 - • Refurbishment Was in Work
 - USA Post Flight Assessment Team Performed Initial Thorough Assessment of Hardware
 - SRBWG Reviewed Post Flight Data and Photography plus Hardware as it was in the Disassembly and Refurbishment Process

Page 12

Preliminary - Investigation Sensitive



Solid Rocket Booster Working Group Agenda

SRB Working Group



- Executive Summary
- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary

Preliminary - Investigation Sensitive

Page 13



Investigation Process


SRB Working Group

SRB Hardware classified into two categories


- Retrieved Hardware
 - Post-Flight Assessment
 - SRBWG Re-Assessment
 - Video and Photography
 - Flight Loads Analysis/Flight Data
 - 10MNL-0035 Requirements Document
- Non-Retrieved Hardware
 - Video and Photography
 - Comparison to Retrieved Hardware with Equal Processing
 - Flight Data (DAS, Telemetry)
 - Documentation Assessment Including:
 - As-designed vs. As-Built
 - Engineering Changes Affecting STS107
 - Problem Reports/Squawks/Non-Conformances
 - SRB Build-up and Consumables
 - Ground Operations Build-up Documents
 - NASA ALERTS
 - Hazard Analysis and CIL Correlation
 - SRB Waiver List Review

Preliminary - Investigation Sensitive

Page 14




SRBWG Philosophy:
***"All Hardware is
 Guilty until
 Proven Innocent."***
John Key



Investigation Process

SRB Working Group




Page 15

Preliminary - Investigation Sensitive



Investigation Process

SRB Working Group



Operational Experience and Design Limits

- Knowledge of both existing data base and design limits (overall and second-by-second) needed to understand hardware performance
- Each Shuttle flight adds to our knowledge and experience base
- Deviations/Exceedances from the experience base result in executing planned activities to understand the “what”, “how” and “why” of event.



Fault Tree Development

- Fault Tree developed and checked against Hazards Analysis and Critical Items List (CIL)



Independent Reviews

- Senior Advisory Group
 - 2 Reviews for Fault Tree Development
 - 3 Reviews for Closure Development
 - 2 Final Presentation Reviews
- MSFC Systems Team – 1 Fault Tree Development Review



SRBWG Fault Tree mapped to MEIC/Systems and CAIB Fault Tree


Preliminary - Investigation Sensitive

Page 16



Investigation Process

SRB Working Group



Fault Tree Closure Process

Closure Rationale Developed jointly by USA/SRBWG/DCMA

- USA Teams provided initial write-up
 - Including input from SRBWG members and DCMA
- USA SRB Chief Engineer Office Review
- SRBWG Chairman/MSFC S&MA performed individual one-on-one reviews with USA team lead and SRBWG discipline/hardware lead for each closure sheet
- • Entire SRBWG and SRB Project Personnel performed final closeout review on each closure sheet. DCMA present at each closure discussions.


Page 17

Preliminary - Investigation Sensitive



Solid Rocket Booster Working Group Agenda

SRB Working Group



- Executive Summary
- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary



Preliminary - Investigation Sensitive

Page 18



Solid Rocket Booster Working Group Fault Tree Multi-Element Blocks


SRB Working Group





Solid Rocket Booster Working Group SRBWG-to-MEICT Mapping

SRB Working Group



G525

B.1.3.1	B.1.3.4.4.1.A	B.1.3.6.4.1.B
B.1.3.1.1	B.1.3.4.4.1.B	B.1.3.6.4.1.1
B.1.3.2.A	B.1.3.4.4.1.1.A	B.1.3.6.4.1.2
B.1.3.2.B	B.1.3.4.4.1.1.B	B.1.3.6.5
B.1.3.2.1	B.1.3.4.4.1.1.1	B.1.3.7.A
B.1.3.2.2	B.1.3.4.4.1.1.2	B.1.3.7.B
B.1.3.2.4.A	B.1.3.4.4.2	B.1.3.7.1
B.1.3.2.4.1	B.1.3.5.A	B.1.3.7.1.1.A
B.1.3.2.4.2	B.1.3.5.B	B.1.3.7.1.1.B
B.1.3.2.4.3	B.1.3.5.C	B.1.3.7.2
B.1.3.2.4.4	B.1.3.5.1	B.1.3.7.2.B
B.1.3.2.5	B.1.3.5.2	B.1.3.7.2.M
B.1.3.3	B.1.3.6.A	B.1.3.7.2.S
B.1.3.4.A	B.1.3.6.B	B.1.3.7.3
B.1.3.4.B	B.1.3.6.1	B.1.3.7.4.1
B.1.3.4.1	B.1.3.6.1.1	B.1.3.7.4.2
B.1.3.4.1.1	B.1.3.6.2	B.1.3.7.5
B.1.3.4.2	B.1.3.6.3	B.1.3.7.6.A
B.1.3.4.2.C	B.1.3.6.3.G	B.1.3.7.6.B
B.1.3.4.2.M	B.1.3.6.4.A	B.1.3.7.6.C
B.1.3.4.2.N	B.1.3.6.4.B	
B.1.3.4.3	B.1.3.6.4.1.A	

G526

B.1.3.1
B.1.3.2.4.3
B.1.3.4.4.2
B.1.3.6.2

G527

B.1.3.5.1 B.1.3.6.4.1.2
B.1.3.5.2 B.1.3.6.4.1.A
B.1.3.5.A-C B.1.3.6.4.1.B
B.1.3.4.B B.1.3.6.4.A
B.1.3.4.2 B.1.3.6.4.B
B.1.3.4.4.1.1.1 B.1.3.7.A
B.1.3.4.4.1.1.2 B.1.3.7.4.1
B.1.3.4.4.1.1.A B.1.3.7.4.2
B.1.3.4.4.1.1.B B.1.3.7.B
B.1.3.4.4.1.A B.1.3.7.2
B.1.3.4.4.1.B B.1.3.7.2.B
B.1.3.4.4.2 B.1.3.7.2.M
B.1.3.6.A B.1.3.7.2.S
B.1.3.6.2 B.1.3.7.6.A-C
B.1.3.6.4.1.1

G649


B.1.3.6.1
B.1.3.6.1.1
B.1.3.7.1

G814

B.1.1.1.1.1 B.1.1.2.3.1.2.2
B.1.1.1.2.A-G B.1.2.1, B.1.2.2
B.1.1.2.A B.1.3.4.4.1.1.1
B.1.1.2.B B.1.3.4.4.1.1.2
B.1.1.2.1 B.1.3.4.4.1.1.A
B.1.1.2.1.D B.1.3.4.4.1.1.B
B.1.1.2.2 B.1.3.6.4.1.1
B.1.1.2.3 B.1.3.6.4.1.2
B.1.1.2.3.1.1.1 B.1.3.6.4.1.A
B.1.1.2.3.1.1.2 B.1.3.6.4.1.B
B.1.1.2.3.1.2.1

Preliminary - Investigation Sensitive

Page 20



SRB Working Group

FT Cause ID#	Fault Tree (FT) Block Name	Level 2
B.1.1	Anomalous Loads and Environments on SRB Adversely Affect Mission, Vehicle & Crew	G499/G814
B.1.1.1 ⑥	Extreme Environments Adversely Affect SRB or SRB/ET Interface	
B.1.1.1.1	Extreme Natural Environments Adversely Affect SRB or SRB/ET Interface	
B.1.1.1.2.A	Adverse Effects From Conducted or Radiated Electro Magnetic Interface (EMI)	
B.1.1.1.2.B	Adverse Aerothermal Effects During Ascent	
B.1.1.1.2.C	Adverse Vibro-Acoustic Effects While on Pad or During Ascent	
B.1.1.1.2.D	Adverse Vehicle Dynamics Effects While on Pad or During Ascent	
B.1.1.1.2.E	Adverse Aerodynamic Effects During Ascent	
B.1.1.1.2.F	Improper Venting During Ascent	
B.1.1.1.2.G	Pryo Shock While on Pad or During Ascent	
B.1.1.2 ⑥	Anomalous Loads Adversely Affect SRB or SRB/ET Interfaces	
B.1.1.2.1	Anomalous Loads During Prelaunch Operations	
B.1.1.2.1.D	Adverse Loads Induced by SSME Thrust Build Up	
B.1.1.2.A	Anomalous Induced Loads Caused by Holddown Stud Hangup	
B.1.1.2.2	Anomalous Loads During Ascent	
B.1.1.2.B	Anomalous Loads During Liftoff	
B.1.1.2.3	Anomalous Loads During Booster Separation	
B.1.1.2.3.1.1.1	Premature Ignition (Aft BSM)	
B.1.1.2.3.1.1.2	Low/Inadequate Thrust Output for any Two BSMs (Aft BSM)	
B.1.1.2.3.1.2.1	Premature Ignition (Forward BSM)	
B.1.1.2.3.1.2.2	Low/Inadequate Thrust Output for any Two BSMs (Forward BSM)	


Page 21

Preliminary - Investigation Sensitive



Solid Rocket Booster Working Group Fault Tree Multi-Element (2 of 5)


SRB Working Group



FT Cause ID#	Fault Tree (FT) Block Name	Level 2
B.1.2.1	Anomalous Electrical & Instrumentation Subsystem Performance	
B.1.2.1.A	Anomalous SRB/ET Separation Performance	G499/G814
B.1.2.1.E	Anomalous SRB Guidance, Navigation & Control Performance (Rate-Gyro)	G499/G814
B.1.2.1.F	Anomalous SRB Electrical Power/Data Cable Performance	G499/G814
B.1.2.2	Anomalous Thrust Vector Control (TVC) Subsystem Performance	G499/G814
B.1.3.1	Nose Cap Assembly Damage/Malfunction Causes Debris	
B.1.3.1.3.E	Overload [Nose Cap Fastener]	G524/G526
B.1.3.2. ③	Frustum Assembly Damage/Malfunction Causes Debris	
B.1.3.2.4.3.F	Aerodynamic Loading Causes Debris	G524/G526

Preliminary - Investigation Sensitive

Page 22




SRB Working Group

Preliminary - Investigation Sensitive



Solid Rocket Booster Working Group Fault Tree Multi-Element (4 of 5)

SRB Working Group



FT Cause ID#	Fault Tree (FT) Block Name	Level 2
B.1.3.5.0	Tunnel Cover/Floor Plate Assembly Damage/Malfunction Causes Debris	G524/G527
B.1.3.5.1	Loss of Thermal Protection System (TPS) Causes Debris [Tunnel Cover/Floor Plate Assembly]	
B.1.3.5.A	Structural Damage to Tunnel Cover Assembly Causes Debris	
B.1.3.5.B	Loss of Electrical Cables and Connector Components causes Debris [Tunnel Cover/Floor Plate Assy]	
B.1.3.5.2	Loss of Tunnel over/Floor Plate Components Causes Debris (SRB/RSRM)	
B.1.3.5.C	Improper Operation of Pyrotechnic Components Causes Debris [Tunnel Cover/Floor Plate Assembly]	
B.1.3.6.0	ETA Ring/Aft Attach Strut Assembly Damage/Malfunction Causes Debris	
B.1.3.6.A	Loss of Elec. Breakaway Cables & Connector Components (Sep. Plane) [ETAR/Aft Attach Strut Assy]	G524/G527
B.1.3.6.1	Loss of Thermal Protection System (TPS) Causes Debris [ETAR/Aft Attach Strut Assy]	G524/G649
B.1.3.6.2	Aft Strut Component Failure (ET Strut Half)	G524/G527
B.1.3.6.2.3.1.E	Overload [Aft Strut ET Fastener]	G524/G526
B.1.3.6.4	Aft Separation Bolt Components Causes Debris	G524/G527
B.1.3.6.4.A	No Separation Causes Debris	
B.1.3.6.4.B	ETA Ring Structural Failure	
B.1.3.6.4.1	Improper Separation Causes Debris	G499/G814
B.1.3.6.4.1.A	Failure Outside of Fracture Plane Causes Debris	
B.1.3.6.4.1.B	Recontact Causes Debris (Strut Half)	
B.1.3.6.4.1.1	Material Defects Causes Debris	
B.1.3.6.4.1.2	Manufacturing Defect Causes Debris	


Preliminary - Investigation Sensitive

Page 24



Solid Rocket Booster Working Group Fault Tree Multi-Element (5 of 5)

SRB Working Group




FT Cause ID#	Fault Tree (FT) Block Name	Level 2
B.1.3.7.®	Aft Skirt Assembly Damage/Malfunction Causes Debris	
B.1.3.7.A	Loss of Electrical Breakaway Cables & Connector Components (Separation Plane) [Aft Skirt]	G524/G527
B.1.3.7.B	Aft Skirt Assembly Structural Failure Causes Debris	G524/G527
B.1.3.7.1.D	Loss of RT455 without Hypalon From Aft Skirt Assembly Causes Debris	G524/G649
B.1.3.7.1.E	Loss of BTA without Hypalon From Aft Skirt Assembly Causes Debris	G524/G649
B.1.3.7.1.G	Loss of RTV133/RTV108 From Aft Skirt Assembly Causes Debris	G524/G649
B.1.3.7.2	Loss of Aft Skirt Components Causes Debris	G524/G527
B.1.3.7.4	Improper Operation of Pyrotechnic Components Causes Debris [Aft Skirt]	G524/G527
B.1.3.7.4.1	Improper Operation of SRB/MLP Holddown Release	
B.1.3.7.4.2	Improper Operation of Booster Separation Motor Ignition Components	
B.1.3.7.6	Loss of MLP Holddown Components Causes Debris	G524/G527
B.1.3.7.6.A	Loss of Aft Skirt Shoe Hardware Causes Debris (includes Shims and Ground Straps)	
B.1.3.7.6.B	Loss of GN2 Purge Line Assembly Causes Debris	
B.1.3.7.6.C	Loss of Holddown Hardware Causes Debris (includes Stud Washer, Nut & Breaklink Nut)	

Preliminary - Investigation Sensitive



Fault Tree Block Presentation Sequence

SRB Working Group



File #	Block ID.	Order of Presentation	Number of Closure Sheets	Title or related areas
File #1	B.1.1	6	18	Anomalous Loads and Environments on SRB Adversely Affect Mission, Vehicle and Crew
File #2	B.1.2	7	2	Anomalous Performance of Active Subsystems
File #3	B.1.3.1	5	2	Nose Cap Assembly Damage/Malfunction Causes Debris
File #4	B.1.3.2 B.1.3.3	2	11	Frustum Assembly Damage/Malfunction Causes Debris, Parachutes
File #5	B.1.3.4	1	20	Forward Skirt Assembly Damage/Malfunction Causes Debris
File #6	B.1.3.5 B.1.3.6	4	19	Tunnel Cover/Floor Plate, ET Attach Ring and Aft Attach Strut Cause Debris
File #7	B.1.3.7	3	16	Aft Skirt Assembly Damage/Malfunction Cause Debris
File #8	Executive Summary/Presentation			
Total			88	



Preliminary - Investigation Sensitive

Page 26




Fault Tree Block Presentation Sequence


SRB Working Group




SRB Pictorial




Photographic/Film Data



Fault Tree Block Closure Sheet






Engineering Data




Page 27


Fault Tree Branch Summary Sheet





Fault Tree Branch



Multi-Element Matrix



Preliminary - Investigation Sensitive




- List of Members, Advisors, Observers, and Others
- Method of Investigation
 - Working Group Organization
 - Special Circumstances
 - Investigation Process
- Fault Tree Closure Summary
- Summary



Summary

SRB Working Group



- All Multi-Element Fault Tree Blocks Have Been Addressed Individually or as a Sub-Block to a Higher Level Closure Sheet.
- All SRB Systems Performed Nominally within Specifications and with No Unexplainable Experience-Base Deviations.
- Solid Rocket Boosters are Known STS Debris Generators:
 - All Debris Generating Events Have Been Identified
 - Debris at Liftoff
 - Debris during Flight
 - Debris at Separation
 - Debris after Separation
- Four Bolt Catcher Fault Tree Blocks Remain Open until after Testing is Complete (Estimated Completion 6/9/03).
- Investigation Results Thus Far Indicate SRBs did not Cause Loss of STS-107.

SRB Launch through Recovery Environments

Page 29

Preliminary - Investigation Sensitive

THIS PAGE INTENTIONALLY LEFT BLANK